

Community Development Department • Building Inspection Division 500 Castro Street • Post Office Box 7540 • Mountain View, California 94039-7540 • 650-903-6313 • FAX 650-962-8501

## SKYLIGHT FRAMING DETAIL

**Roof Framing Around Openings** 

## 2010 California Residentail Code, Section R802.9 2010 California Building Code, Section 2308.10.4.3

- Headers with a span exceeding 4' must be framed with trimmers and header rafters that are doubled or of lumber of equivalent cross-section.
- The ends of header rafters more than 6' in length shall be supported by framing anchors or rafter hangers unless the rafters bear on a beam, partition or wall.

